ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura

Street ID	Street Name	Significant Landmark
W0363, W0286, W0334, W0324, W0417, W0332, W0320, W	R H B Colcny 1st Main Rd, 4th Crs, Maheshwari Nagar, R H B Colcny, 5th Crs, R H B Colcny, 3rd Crs, N	D Pillappa Layout

Segment No.	Total Length (m)
7/C-W0363/S124247	219.42

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	121.99	77.601799	13.066886	77.601711	13.065787	Cross road	Dead End
2	97.43	77.599778	13.063775	77.600676	13.063775	Ashwath Katte Road	Cross road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads & drains from D Pillappa layout to amruthahalli lake bund road in amruthahalli in ward no.07 Byataranapura.	2500000	2019-20

Year	Type of Work	Other Work Type
2019 - 2020	Road	

Tender	Work Details	Job No. / Work Code
Tender	1.Providing and laying Cement Concrete Road.2.Providing and laying Kerb Stones.	007-20-000092

Work Order No.	Work Order Date	Period of Extention
BBMP/EE/BTP/WO/36/20-21	14/07/2020	

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
22/10/2020	21/10/2023	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Vishnu M Gowda		0.00

Phone No.	E-Mail ID
9972852240	

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Pushpalatha.N.D

Date of Inspection	Remarks
27/10/2020	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0363, W0286, W0334, W0324,

Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.S.P.Ranganath	27/10/2020	26/11/2020	As proposed
SE	Vijay Kumar Haridas	27/10/2020	26/11/2020	Forwarded
EE	Mohan Das H T	27/10/2020	26/11/2020	Approved
AEE	G Srinivasa Murthy	27/10/2020	26/11/2020	Verified
AE	Pushpalatha.N.D	27/10/2020	26/11/2020	Mobile Verification Done
AE	Pushpalatha.N.D	27/10/2020	26/11/2020	Forwarded

Pushpalatha.N.D
AE(~~AE~~)

Assistant Executive Engineer
Yelahanka Sub Division
Yelahanka Zone, B.B.M.P.
Bangalore.

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0363, W0286, W0334, W0324, W0417, W